DEPARTMENT OF TRANSPORTATION

FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

Blackwell, Michael	Inspec	ctor's Name	Ins	Inspector's Signature							Ins	pector's ID N	o. Report	No.	Date						
Railroad Company Name & Address ALASKA RR CORP. 4923 N. Kipling Dr. Wasilla AK 99654 RRCC RECL RRCC R	F						F								F	Report	110.	уу	mm	dd	
R	Blacl	kwell, Micha									1	11265	148	3	2014	09	26				
Age						R/C	2	Divisi	ion		RR/Co.	Representati	ve (Rece	eipt Acknov	ledged)						
Wasilla AK 99654 ARR Subdivision Title SYSTEM Email sewtrain557@gmail.com Signature From: City WASILLA Codes Codes Codes From Latitude From Longitude County MATANUSKA SUSITNA C170 County MATANUSKA SUSITNA C170 Inspection Point WASILLA STEAM SHOP To Latitude To Latitude Code: 230 Units: 1 Sub Units: 0 Inspection Point WASILLA STEAM SHOP To Longitude Code: Subdivision From Latitude From Longitude Codes Codes From Latitude To Latitude Codes Codes Codes From Latitude From Longitude Codes Codes Codes From Longitude Codes Codes Codes From Latitude Codes Codes Codes From Latitude Codes Codes	ALA	SKA RR CC						R	SYSTEM			Name	Patrick Durand								
Wasilla AK 99654 ARR SYSTEM Email sewtrain557@gmail.com Signature From: City WASILLA Codes 2790 Destination City & County Codes Trom Latitude From Longitude County MATANUSKA SUSITNA C170 County Mile Post: From To Inspection Point WASILLA STEAM SHOP To Longitude Activity Code: 230 Units: 1 Sub Units: 0 Inspection Point WASILLA STEAM SHOP To Longitude From Latitude From Latitude From Latitude From Latitude From Latitude From Latitude From Longitude From Longitude From Longitude From Longitude From Longitude From Latitude From Latitude From Latitude From Longitude Fr	4923	N. Kipling I	Or.								Co.										
Signature Sign															Title						
Codes From Latitude Codes AK	Wasi	lla			AK	99	99654				RR	SYSTEM			Email	sewtraii	sewtrain557@gmail.com				
State AK O2 City From Longitude County MATANUSKA SUSITNA C170 County MATANUSKA SUSITNA C170 County MATANUSKA SUSITNA C170 County Mile Post: From To Inspection Point WASILLA STEAM SHOP To Longitude Activity Code: 230 Units: 1 Sub Units: 0 Item Initials/Milepost Equipment/Track # Type/Kind 49 CFR/ USC STM 230 Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Written Notification to Comments on back? Coden Pater mindid/vovv): Codes From Longitude Codes From Longitude Fr												Signatu				re					
County MATANUSKA SUSITNA C170 County Mile Post: From To Inspection Point WASILLA STEAM SHOP To Latitude Activity Code: 230 Units: 1 Sub Units: 0 Lequipment/Track # Type/Kind 49 CTR/ USC STM 230 Defect Subrule Speed Class Train #/Site SNFR* RCL** # of Occ.*** Code WASILLA SHOP N N N 0 Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Witten Notification to Written Notification to Railroad Action Code Railroad Action Code Railroad Action Code Comments on back? Comments on back?	L TTT A CTT T A						790 Destination City &				nty	(Codes	From Lat	From Latitude				
Mile Post: From To Inspection Point WASILLA STEAM SHOP To Longitude Activity Code: 230 Units: 1 Sub Units: 0 Item Initials/Milepost Equipment/Track # Type/Kind 49 CFR/ USC STM 230 Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Yes Written Notification to Railroad Action Code Page(mm/d/(vvvv)) Comments on back? Comments on back? Comments on back?	State AK)2 City									From Lor	From Longitude				
Activity Code: 230	County MATANUSKA SUSITNA (C170 County									To Latitude					
Code: 230 Units: 1 Sub Units: 0 Sub Units: Speed Class Train #/Site SNFR* RCL** # of Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.*** Code Occ.*** Code Occ.*** Code Occ.** Code Occ.***	Mile Post: From To						Inspect	SILL	LLA STEAM SHOP					To Longitude							
Sub Units: O		y	230																		
Item Initials/Milepost Equipment/Track # Type/Kind 49 CFR/ USC STM 230 Defect Subrule Speed Class Train #/Site SNFR* RCL** # of Occ.*** Code Occ.*** Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Written Notification to Recommended Yes Railroad Action Code Reailroad Action Code Reailroad Company Reailroad Action Code Reailroad Action Code Reailroad Company Reailroad Action Code Reailroad Action Code Reailroad Recomments on back?	Units:		1																		
Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Latitude: Railroad Action Code Pate(mm/dd/vyvy): Comments on back?	Sub U	nits:	0																		
1 ARR 557 STM 230 WASILLA SHOP N N 0 Description - [** Comment to Railroad/Company **] Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Latitude: Longitude: Written Notification to Railroad Action Code Railroad Railroad Action Code Railroad Railroad Action Code Railroad Rail	Item Initials/Milepo		ost Equip		ment/Track #			Defe	et Subr	ule		Speed Cla		Class	Train #/Site	#/Site		* RCL**		Activity	
Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Railroad Action Code Pate(mm/dd/yyyy): Comments on back?	1	1 ARR		557		1		5							WASILL	A SHOP N		N		Code	
Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox. The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Railroad Action Code Pate(mm/dd/yvyv): Comments on back?																					
The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Latitude: Longitude: Written Notification to Railroad Action Code Pate(mm/dd/yyyy): Comments on back?		-																			
The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Latitude: Longitude: Written Notification to Railroad Action Code Pate(mm/dd/yyyy): Comments on back?	Inspected the boiler and firebox on engine ARR 557. The tubes were removed for inspection. This steam locomotive is in the process of total restoration. No exceptions were taken during the inspection of the boiler or firebox																				
Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Yes No Latitude: Longitude: Written Notification to Railroad Action Code Date(mm/dd/yyyy): Comments on back?	1			U	1																
Violation Recommended	The ARR 557 is estimated to be ready for a hydrostatic test in 2016. The restoration of the ARR 557 to date is very impressive, being restored with quality and pride.														d pride.						
Written Notification to Railroad Action Code Date(mm/dd/yyyy): Comments on back?	Seal Applied Seal Remo					al Removed	ved				Hazard Class				UN/NA ID						
Written Notification to Railroad Action Code Date(mm/dd/yyyy): Comments on back?																					
D 1 A Q C 1	Violation Recommended Yes V					✓ No	To Lat				titude:				L	Longitude:					
FRA of Remedial Action is: Required Optional Date(mm/dd/yyyy): Comments on back?	Written Notification to Railros									Code Doto(mm/44/)								Com	anto on 1-	ale?	
L CONTRACTOR OF THE CONTRACTOR	FRA o	f Remedial A	action i	s:	Required	✓ Option	al	Date(IIIII/C						111/UU/Y	ууу):			Comm	ciits on Da	ICK!	

OMB Approval No.: 2130-0509